## Council

FROST PARK - DRAINAGE

Attachment One - Photos

Attachment Two - Site Repairs Diagram

Meeting Date: 08 September 2020

Number of Pages: 4

## Frost Park – Drainage Photos – 26 August 2020




Pavillion roof water collection sump looking south. Note inlet of downpipes is higher than inlet of subsoil. Outlet from sump (not shown) is higher than subsoil piping.



Ag Shed water collection sump. Note that LHS subsoil pipe leads back towards Pavillion and is lowest point in the sump. ie Flow is backwards to what it should be.



Western side of track where under track culvert begins. The subsoil system from the pavillion area is supposed to terminate here but note that there is no water flow.



Looking eastwards under track through culvert system. Note rotted and cracked timber, cracked and bowing side walls. Some grass roots can be seen growing down through the lid.

